

PRODUCT CHANGE NOTIFICATION

Notification number: 2022-0001 (V2)	Date: 7 January 2022
-------------------------------------	----------------------

Affected part numbers:	1.) DA56-11HWA 2.) DC-7G3HWA 3.) DD-12HWP 4.) DD-8G4HWP 5.) KM-23HD-F 6.) KM-27HD-01 7.) KP-2012HD 8.) KP-3216HD 9.) KPA-3010HC 10.) L-1034HDT 11.) L-113HDT 12.) L-13HD 13.) L-144HDT	14.) L-2060HD 15.) L-34HD / L-34HD-TNR2.54 16.) L-36BHD 17.) L-383HDT 18.) L-424HDT 19.) L-42A8HDT 20.) L-483HDT 21.) L-53HD / L-53HD-TNR2.54 22.) L-56BHD 23.) L-7104HD / L-7104HD-TNR2.54 24.) L-7113HD / L-7113HD-TNR2.54 25.) L-934HD / L-934HD-TNR2.54 26.) SA / SC36-11HWA 27.) SA / SC52-11HWA
Change description:	Standard red H chip will be replaced by high efficiency red I / E chip	
Reason for change:	Chip supplier will no longer supply the standard red H chip contained in above PNs. Suggest to change to alternative high efficiency red I / E chip as replacement.	
Anticipated impact of change:	The physical properties are identical and the electrical properties are considered compatible. Customer can check the specs and request samples for approval.	
Part numbers to substitute affected parts:	1.) DA56-11EWA 2.) DC-7G3EWA 3.) DD-12EWP 4.) DD-8G4EWP 5.) KM-23ID-F 6.) KM-27ID-01 7.) KP-2012ID 8.) KP-3216ID 9.) KPA-3010EC 10.) L-1034IDT 11.) L-113IDT 12.) L-13ID 13.) L-144IDT	14.) L-2060ID 15.) L-34ID / L-34ID-TNR2.54 16.) L-36BID 17.) L-383IDT 18.) L-424IDT 19.) L-42A8IDT 20.) L-483IDT 21.) L-53ID / L-53ID-TNR2.54 22.) L-56BID 23.) L-7104ID / L-7104ID-TNR2.54 24.) L-7113ID / L-7113ID-TNR2.54 25.) L-934ID / L-934ID-TNR2.54 26.) SA / SC36-11EWA 27.) SA / SC52-11EWA
Last Time Buy:	Kingbright accept Last Time Buy of the affected part numbers until 31 March 2022 as long as chip stock is available with delivery date no later than 30 June 2022.	

With best regards

Udo Reinhold

Managing Director

Mailto: udo.reinhold@kingbright-europe.de